



Test Report NO.: BNGJTTVR08516757 Issued Date: 2019-08-05 Page 1 of 2 Applicant: Storex Industries Corp. The following sample(s) was/were submitted and identified on behalf of the client as: Cover for 4 gallon bin, translucent Sample Name: STOREX Manufacture: Country of Origin: CANADA Country of Destination: Canada STOREX Supplier: Sample Received Date: 2019-07-23 **Testing Period:** 2019-07-23~2019-08-05

Reference requested:

CPSIA H.R.4040 & H.R.2715, Total Lead content analysis is performed by AAS.

Testing Results:

Please refer to next page(s)

Edited by:

Checked by:

Approved by:

The page below is blank

(C) Hotline 400-819-5688 www.ponytest.com

 Pony Testing Group Shanghai Co.,Ltd.
 Company Address:2F.,No.7 Building, No.99, Wen Xiangdong Road,SongJiang District,Shanghai,China
 Tel:021-37895599

 Test Address:2/3/4/6/F., Building 35, No.680, Guiping Road, Xuhui District, Shanghai, China
 Tel:021-37895599





Test Report NO.: BNGJTTVR08516757

7 Issued Date: 2019-08-05

Page 2 of 2

Total Lead- CPSC-CH-E1002-08.3 Test Results (Unit: mg/kg)

| | | | · | |
|------------|-----------|---------------|----------------------|----------------------------------|
| Test Item | MDL | Limits | Test Result | Evaluation |
| Total Lead | 1 | 100 | N.D. | Qualified |
| | Test Item | Test Item MDL | Test Item MDL Limits | Test Item MDL Limits Test Result |

Test Components: Substrate (non-metal)

- Note:
 - (1) mg/kg = ppm
 (2) N.D. = Not Detected (<MDL)
 - (3) MDL = Method Detection Limit

Sample No. & Photo:



Pony authenticate the photo on original report only ***End of Report***

C Hotline 400-819-5688 www.ponytest.com

Pony Testing Group Shanghai Co.,Ltd. Company Address:2F.,No.7 Building, No.99, Wen Xiangdong Road,SongJiang District,Shanghai,China Tel:021-37895599 Test Address:2/3/4/6/F., Building 35, No.680, Guiping Road, Xuhui District, Shanghai, China